


# ARE YOU READY FOR JOINT COMMISSION INSPECTIONS ON YOUR EMERGENCY SHOWER AND EYE WASH EQUIPMENT?



## FINDINGS

More than 88% of Emergency Shower and Eyewash units inspected are NOT ANSI Z358.1 compliant.

### Common Issues mean Hidden Risks

- Low Flow
- Uneven Flow
- Improper Installation

Haw Services can help maintain accreditation in CAPS laboratories by ensuring your emergency shower eyewash equipment is compliant.



## OUR SERVICES INCLUDE:




Comprehensive ANSI Z358.1 Inspections as required by CMS and Joint Commissions



Equipment Installation and Repair on all Haws brands



Reduce chances of Legionella exposure by properly flushing shower and eyewash equipment.



Detailed full color report, documenting each piece of emergency equipment in pictures along with its ANSI/ISEA Z358.1 compliance.

